Installing RLF Files in Carveco

Thank you for purchasing this RLF pack from CNC Carver's Workshop!

Follow these steps to import and use your RLF files in Carveco:

1. Unzip the download file:
   - Extract all contents to a folder on your computer.
   - You'll see a folder containing multiple .RLF files and this PDF.

2. Move the folder into your Carveco Relief Library:
   - Navigate to your Documents folder.
   - Open: Documents > Carveco > Relief.
   - Inside, you will see other folders (e.g., Animals, Signs, etc.).
   - Copy the entire folder you just unzipped into this 'Relief' folder.
   - Make note of the folder name, as this will appear in Carveco.

3. Open Carveco:
   - Go to the Relief Clipart Library.
   - You should now see your new folder listed in the library.
   - Open it to view and use all of your new RLF files.

4. Add to a project:
   - Double-click or drag and drop reliefs into your current model.
   - Resize, position, and combine them as needed.
   - These files have been optimised for stacking and working together.
   - For tips on how to build your composite image, visit our website:
     www.cnccarverworkshop.co.uk

5. Set your toolpaths:
   - Use a roughing pass with a 3mm end mill.
   - Use a finishing pass with a 1mm or 1.5mm ball nose bit.
   - Adjust depth and step-over to retain detail.

6. Preview and export your toolpaths:
   - Simulate your toolpaths to confirm everything looks correct.
   - Export your G-code for your CNC machine.

For support, visit: facebook.com/groups/cnccarver
Or email: support@cnccarverworkshop.co.uk

■ For how-to videos and updates, visit: www.cnccarverworkshop.co.uk

Happy carving!